

Quick Start Guide

PPTIIA



Xiamen Hanin Electronic Technology Co., Ltd.
 ADD: Room 305A Angye Building, Pioneering Park,
 Torch High-tech Zone, Xiamen, China 361009
 TEL: +86-(0)592-5885993
 FAX: +86-(0)592-5885992
 WEB: www.hpirt.com

Packing List

Standard Accessories

- Printer
- Quick Start Guide
- Power Adapter varies by locale or region
- Power Cord varies by locale or region




- CD




Optional Accessories

- USB Cable
- Parallel Cable
- Serial Cable



Appearance and Part Names


Front




- Control Panel
-
- Power LED
 - Error LED
 - FEED button

Rear


- Model 1




- Model 2




- Model 3



- Model 4





Connect the Power Supply



1. Turn off the printer power.
2. Plug in the cable connector of the AC adapter to the power connector at the rear of the printer.
3. Connect the AC power cord to the inlet of AC adapter, and insert the AC power cord plug into a suitable wall outlet.



Open the Printer Cover

Open the printer cover by pressing up one side of cover open lever.




Install the Roll Paper

1. Open the printer cover.
2. Remove the used roll paper core, if there is one.
3. Install the roll paper in the correct direction as shown in the figure below.



4. Pull out some roll paper, and press down the center of the printer cover to close the cover.



5. Tear off any excess paper in the direction of the side of the printer.

